




## 2NZ



mm

Order Code	$\varnothing d_1$ (e8)	$l_2$	$l_3$	$l_1$	$\varnothing d_3$	$\varnothing d_2$ (h8)
2NZ0502	0.5	1.0	2	50	0.47	6.0
2NZ0504	0.5	1.0	4	50	0.47	6.0
2NZ0506	0.5	1.0	6	50	0.47	6.0
2NZ1004	1.0	1.5	4	50	0.97	6.0
2NZ1006	1.0	1.5	6	50	0.97	6.0
2NZ1008	1.0	1.5	8	50	0.97	6.0
2NZ1010	1.0	1.5	10	50	0.97	6.0
2NZ1012	1.0	1.5	12	50	0.97	6.0
2NZ1504	1.5	2.0	4	50	1.47	6.0
2NZ1508	1.5	2.0	8	50	1.47	6.0
2NZ1510	1.5	2.0	10	50	1.47	6.0
2NZ1512	1.5	2.0	12	50	1.47	6.0
2NZ1516	1.5	2.0	16	50	1.47	6.0
2NZ2010	2.0	3.0	10	50	1.95	6.0
2NZ2012	2.0	3.0	12	50	1.95	6.0
2NZ2016	2.0	3.0	16	50	1.95	6.0
2NZ2020	2.0	3.0	20	50	1.95	6.0
2NZ2510	2.5	3.0	10	50	2.45	6.0
2NZ2512	2.5	3.0	12	50	2.45	6.0
2NZ2516	2.5	3.0	16	50	2.45	6.0
2NZ2520	2.5	3.0	20	50	2.45	6.0
2NZ3010	3.0	4.0	10	50	2.90	6.0
2NZ3012	3.0	4.0	12	50	2.90	6.0
2NZ3016	3.0	4.0	16	50	2.90	6.0
2NZ3020	3.0	4.0	20	50	2.90	6.0
2NZ4010	4.0	4.0	10	50	3.90	6.0
2NZ4016	4.0	4.0	16	50	3.90	6.0
2NZ4020	4.0	4.0	20	50	3.90	6.0